10/680,633

PATENT 128875

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 6,761,629 B1

Issued: July 13, 2004

Inventors: Parker et al.

Assignee: General Electric Company

For: METHODS AND SYSTEMS FOR

DETECTING GAS TURBINE ENGINE FUEL

LEAKS

Certificate

JUL 0 6 2005

of Correction

CERTIFICATE OF MAILING

I certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to Attention Certificate of Corrections Branch, Commissioner to Payents, P. G. Box 1450, Alexandria, VA

22313-1450., on June 28, 2005.

Robert B. Reeser III Reg. No. 45,548

Hon. Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450.

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT UNDER 37 C.F.R. 1.322(a)

Sir:

Attached, in duplicate, is Form PTO/SB/44 with one copy being suitable for printing.

In Claim 5, column 6, line 13, delete "duet" and insert therefor -- duct --.

The correction is not due to any error by applicants and no fee is due.

The Assignment for this patent is recorded on Reel 014729/ Frame 0980.

Date: 🗸

Robert B. Reeser III

Reg. No. 45.548

Respectfully

ARMSTRONG TEASDALE LLP One Metropolitan Square, Suite 2600

St. Louis, Missouri 63102-2740

(314) 621-5070

Approved for use through 04/30/2007. OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

: 6,761,629 B1

DATED

: July 13, 2004

INVENTORS(S)

: Parker et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Claim 5, column 6, line 13, delete "duet" and insert therefor -- duct --.

MAILING ADDRESS OF SENDER: Robert B. Reeser III Armstrong Teasdale LLP One Metropolitan Sq., Suite 2600 St. Louis, MO 63102 PATENT NO. 6,761,629 B1

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 6,761,629 B1

Issued: July 13, 2004

Inventors: Parker et al.

Assignee: General Electric Company

For: METHODS AND SYSTEMS FOR

DETECTING GAS TURBINE ENGINE FUEL

LEAKS

CERTIFICATE OF MAILING

I certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelop addressed to Attention Certificate of Corrections Branch, Commissioner to Payents, P.O. Box 1450, Alexandria, VA

22313-1450., on June 28, 2005.

Robert B. Reese Reg. No. 45,548

Hon. Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450.

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT UNDER 37 C.F.R. 1.322(a)

Sir:

Attached, in duplicate, is Form PTO/SB/44 with one copy being suitable for printing.

In Claim 5, column 6, line 13, delete "duet" and insert therefor -- duct --.

The correction is not due to any error by applicants and no fee is due.

The Assignment for this patent is recorded on Reel 014729/ Frame 0980.

Date: XX K

Robert B. Reeser III

Reg. No. 45.548

Respectfully

ARMSTRONG TEASDALE LLP One Metropolitan Square, Suite 2600 St. Louis, Missouri 63102-2740

(314) 621-5070

Approved for use through 04/30/2007. OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

: 6,761,629 B1

DATED

: July 13, 2004

INVENTORS(S)

: Parker et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Claim 5, column 6, line 13, delete "duet" and insert therefor -- duct --.

MAILING ADDRESS OF SENDER: Robert B. Reeser III Armstrong Teasdale LLP One Metropolitan Sq., Suite 2600 St. Louis, MO 63102 PATENT NO. 6,761,629 B1

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

JUL - 7 2005